

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

JENNE FARM, BARN
538 Engle Road
Coupeville vicinity
Island County
Washington

HABS WA-250-A

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Anne E. Kidd, photographer, April 2006

- | | |
|------------|--|
| WA-250-A-1 | THE JENNE BARN, MILK HOUSE, AND GARAGE/WORKSHOP, LOOKING EAST FROM DRIVEWAY |
| WA-250-A-2 | INTERIOR OF JENNE BARN GROUND FLOOR. (The Jenne milking stanchions can be seen on the left. The space that originally served as the milking parlor has now been converted into animal pens for goats, chickens, and pigs.) |
| WA-250-A-3 | GROUND FLOOR OF JENNE BARN LOOKING EAST. (The barn's ground floor is used for animal pens. On the left is an area enclosed for chickens. The Jenne milking stanchions remain along the south end of the barn.) |

JENNE FARM, BARN
HABS WA-250-A
INDEX TO PHOTOGRAPHS

- WA-250-A-4 THE HAYLOFT OF THE JENNE BARN, SHOWING ITS UNIQUE CONSTRUCTION. (The barn's gambrel roof is supported by seven bents made-up of diagonal stilts, collar beams, and cross-bracing that tie into the support columns on the ground floor and the sill plates. Also visible are the cables installed across each bent in 2000-02 to reinforce the construction, the hay door at the gable end, and the ladder and opening accessing the barn's ground floor.)
- WA-250-A-5 PRIMARY ENTRANCE INTO THE JENNE FARM, WEST FAÇADE. (The Jenne Barn has board and batten exterior cladding and sits above-grade on a poured concrete foundation. The barn is painted red with white trim. This door is painted green.)